

## Slitter - Rewinders

### Pulsed DC System

#### Problem


Very high static charges are generated on the plastic web during the unwinding and rewinding process. This can cause various problems for converters and their customers, such as:

1. Unpleasant shocks to operators.
2. Dust attraction, leading to contaminated stock.
3. Poor quality wound reels which can be difficult to fit onto machines and may cause feed problems.

#### Solution

The most effective solution is to use Meech Pulsed DC technology, with Model 976 bars positioned as shown. The positioning of a Model 976 bar at the unwind reel is optional but, if fitted, will provide full control of static charges.

Fig.



## APPLICATION NOTE

**Meech International**

2 Network Point  
Range Road, Witney  
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977

email: sales@meech.com