

Bottle Labelling

915 Ionising Bars

Problem


The build up of static electricity on the label web or on the plastic bottles will result in poor label feeding or incorrect label placement and positioning. These problems can result in the mislabelling of bottles, slower production speeds and a higher defect rate.

Solution

Model 915 ionising bars positioned as shown above will neutralise static charges on the label web and the plastic bottles. This solution will allow correct labelling and improve process productivity.

Fig.

Top View



APPLICATION NOTE

Meech International

2 Network Point
Range Road, Witney
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977

email: sales@meech.com