

Conveyor & Bin Ionisation

Pulsed DC System


Problem

1. Static charges on mouldings may cause them to stick to the conveyor.
2. As mouldings fall into the collection bin the "battery effect" can result in a huge charge being accumulated. This causes a high level of dust attraction and operator shocks.

Solution

A Model 976 Pulsed DC bar positioned over the conveyor and collection bin will neutralise the static charges. Mouldings release readily from the conveyor into the collection bin without further dust contamination. Productivity is improved and operator shocks eliminated.

Fig.



Meech International

2 Network Point
Range Road, Witney
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977

email: sales@meech.com