

Print Finishing

Pulsed DC System


Problem

Static charges on the stack of plastic sheets being fed individually (sheet fed) causes them to be attracted together, resulting in mis-feeds or multiple feeds. Such inconsistent feeding causes down time, wastage and reduced running speeds.

Solution

The positioning of a long range Pulsed DC bar above the sheet feeder stack, together with a Model 915 bar below the leading edge of the sheet path to the collection area. This allows the free flow of sheets without any problem of mis-feeding.

Fig.



APPLICATION NOTE

Meech International

2 Network Point
Range Road, Witney
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977
email: sales@meech.com