



Stenter (Flaker) Machines

915 Ionising Bars

Problem

Textiles are delivered directly onto a frame via a swing arm. The following problems can arise:

1. Static causes the product to cling or attract onto the frame sides.
2. Contamination of product due to dust attraction.

Solution

Two Model 915 antistatic bars positioned at the end of the swing arm ensures that the product is fed onto the frame free of static. The Model 915 bars also ensure the product is contaminant-free and the risk of shocks to the operators is removed.

Fig.

APPLICATION NOTE


Meech International

2 Network Point
Range Road, Witney
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977

email: sales@meech.com



Meech International www.meech.com
Meech Static Eliminators Ltd 2005



Offices in
UK - USA - Belgium - Hungary - China