

Injection Moulding

935 Ionising Blower & 957 Air Curtain


Problem

Small, light mouldings can stick to the face of the tool due to static charge. This can result in mould damage and slower production speeds.

Solution

A Meech Model 957 Ionising Air Curtain positioned either above or to the side of the problem area will neutralise the static charge and help remove the parts. Air may be pulsed through the air curtain only when the tool opens to save on air and stop unwanted cooling of the mould tool. A Meech Model 935 ionising blower positioned above the collection bucket will stop static charges being regenerated.

Fig.



APPLICATION NOTE

Meech International

2 Network Point
Range Road, Witney
OX29 0YD, UK

Tel: +44 (0) 1993 706700

Fax: +44 (0) 1993 776977

email: sales@meech.com